



ಇ ಮೇಲ್ :pwdtarikere@gmail.com

ಕರ್ನಾಟಕ ಸರ್ಕಾರ
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ನಂ. ಸ.ಕಾ.ಇಂ./ಲೋ.ಇ/ನಂ-2/ಉವಿತ/ನಿ.ಪ್ರ.ಪ/2021-22

ಇವರಿಗೆ,
ಪ್ರಾಂಶುಪಾಲರು,
ಆರಾಧನ ಹೈಯರ್ ಪ್ರೈಮರಿ ಶಾಲೆ,
ಕೋಡಿ ಕ್ಯಾಂಪ್,
ತರೀಕೆರೆ-577228

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್‌ರವರ ಕಛೇರಿ
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ,
ನಂ. 2 ಉಪವಿಭಾಗ, ತರೀಕೆರೆ.
ದಿನಾಂಕ:

ಮಾನ್ಯರೇ,

ವಿಷಯ: ಪ್ರಾಂಶುಪಾಲರು, ಆರಾಧನ ಹೈಯರ್ ಪ್ರೈಮರಿ ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡುವ ಕುರಿತು

ಉಲ್ಲೇಖ: ತಮ್ಮ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ: Ast/2022/Bsc-01 ದಿನಾಂಕ: 03-06-2022

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ ಉಲ್ಲೇಖಿತ (1) ರ ಪತ್ರದಲ್ಲಿ ~~ಸಂವಿಧಾನ~~ ಆರಾಧನ ಹೈಯರ್ ಪ್ರೈಮರಿ ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡುವಂತೆ ಕೋರಿರುತ್ತಾರೆ. ಸದರಿ ಕಟ್ಟಡದ ಸ್ಥಳ ಪರಿಶೀಲನೆ ನಡೆಸಿ ನಿಗದಿತ ನಮೂನೆಯಲ್ಲಿ ಪ್ರಸ್ತಾವನೆಯನ್ನು ಸಲ್ಲಿಸಲು ಸೂಚಿಸಿದ್ದು, ಅದರಂತೆ ಸ್ಥಳ ಪರಿಶೀಲನೆ ಮಾಡಿ ಶಾಲಾ ಕಟ್ಟಡ ಸುರಕ್ಷಿತವಾಗಿದೆ ಎಂಬ ಮಾಹಿತಿಯನ್ನು ಈ ಮೂಲಕ ಒದಗಿಸಲಾಗಿದೆ.

೮೧೧೮ ಸಿಕ್ರಿಯೆ: ೦೦೬೩೦೦೧, ೮:೧೦-೦೬-೨೦೨೨ ರಂದು ೨೦೦೦=೦೦ (ತುಸು ಖರ್ಚು) ಹಾಗೂ ೪೧೮೩೩ ೫೪೩೩೩೩೩೩೩೩.
ಅಡಕ:-

1) ನಿಗದಿತ ನಮೂನೆ ಪತ್ರ ಲಗತ್ತಿಸಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ,
ನಂ-2 ಉಪವಿಭಾಗ, ತರೀಕೆರೆ.

Visual inspection for Structural stability of the Building:

Sl. No	Requirement	Result	Remarks
Aradhana Higher Primary School, Kodi camp, Tarikere			
1	Visually observed any structural cracks (Cracks in RC beams, Columns, walls, slabs, spalling of concrete, sagging/deflection of beams or slabs, tilting of columns or RC frames (out of plumb)	No	
2	Visually observed any moisture/dampness in the building	No	
3	Visually observed any temporary arrangement for the distressed members	No	
4	Visually observed any non-structural cracks	No	
5	Any non-structural falling hazards, including ceilings, partitions, curtain walls, parapets, fixtures, and other non-structural building elements are found.	No	
6	Any leakages in Terrace, toilets, plumbing lines, drainage lines and overhead tanks are found.	No	
7	Any exposure of reinforcement is found and adequacy of clear cover.	No	
8	Results of the Non destructive test like Rebound hammer test/ Ultrasonic pulse velocity tests/Profometer for rebars (combination of any two is satisfactory?	Yes	Report Enclosed

Assistant Executive Engineer
Public Works Department,
No-02 Sub-Division, Tarikere

